PROPOSED RULES

ceived these documents from the manu- facturer may obtain copies upon request
to the Service Manager, Bell Helicopter Company, P.O. Box 482, Fort Worth, Texas 76101. These documents may also

be examined at the Office of the Regional Counsel, .Southwest Region, FAA, 4400

Blue Mound Road, Fort Worth, Texas,

and at FAA Headquarters, 800 Indepen- dence Avenue, SW., Washington, D.C.

A historical file on this